# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM JUNE 24, 2003

10:00 AM

\_\_\_\_\_\_

#### RETURN HEARING (OLD BUSINESS)

-----

CASE NO: CE03032277 CASE ADDR: 2600 SW 2 C

2600 SW 2 CT REQUEST FOR EXTENSION OF TIME

OWNER: SUNSET COLONY ANNEX INC

INSPECTOR: WAYNE STRAWN

VIOLATIONS: FBC 2301.2.1

THE DESIGN OF THE WOOD SUPPORTING STRUCTURE FOR THE SERVICE ENTRANCE CONDUCTORS AND MAIN DISCONNECTS IS NOT ACCORDING TO GOOD ENGINEERING PRACTICE AND NOT SUFFICIENT TO SUPPORT THE LOADS IMPOSED.

FBC 3401.6

THE WOOD SUPPORTING STRUCTURE FOR THE SERVICE ENTRANCE CONDUCTORS AND MAIN DISCONNECTS HAS SEVERE DETERIORATION CAUSED BY ROT AND IS SAGGING. THIS STRUCTURE DOES NOT SUPPORT THE SERVICE ENTRY AND MAIN DISCONNECTS SAFELY.

ELECTRICAL EQUIPMENT IS DETERIORATED AND NOT BEING MAINTAINED IN A SAFE CONDITION. PROPER GROUNDING IS PREVENTED BY THE DETERIORATED CONDITIONS.

SERVICE RISER CONDUIT IS NOT PROPERLY SECURED TO THE VERTICAL SUPPORT STRUCTURE. THE ORIGINAL SUPPORT METHOD UTILIZED WAS INADEQUATE. NOW THAT THIS ORIGINAL STRAPPING IS DETERIORATED THE RISK OF COMPLETE FAILURE IS SUBSTANTIAL.

ELECTRIC METER CABINETS THROUGHOUT THE PROPERTY ARE NOT BEING MAINTAINED IN A SAFE WORKING CONDITION.

NEC 550-23.(a)

THE TRAVEL DISTANCE FROM THE SERVICE EQUIPMENT TO VARIOUS MOBILE HOMES EXCEEDS THE REQUIRED LIMITS.

NEC 550-23(f)

THE MOUNTING HEIGHT OF MANY OF THE SERVICE PEDESTALS SERVING MOBILE HOMES IS TOO LOW.

NEC 300-5(a)

THE BURIAL DEPTH OF THE ELECTRICAL CONDUITS THAT SUPPLY POWER TO THE POWER PEDESTALS IS MUCH LESS THAN THE REQUIREMENTS.

47-21.8

THE LANDSCAPING IS NOT BEING MAINTAINED ACCORDING TO THE APPROVED PLAN ON FILE.

\_\_\_\_\_\_

## HEARING COMPUTER SCHEDULED

CACE NO. CE03051130

CASE NO: CE03051139
CASE ADDR: 3890 DAVIE BLVD

OWNER: ARCIERO, STEPHEN FRANCIS

INSPECTOR: THOMAS CLEMENTS

VIOLATIONS: NFPA 1 1-4.4

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM JUNE 24, 2003

10:00 AM

UNABLE TO GAIN ENTRY TO PERFORM FIRE SAFETY REINSPECTION.

\_\_\_\_\_

RETURN HEARING (OLD BUSINESS)

\_\_\_\_\_\_

CASE NO: CE03030541

CASE ADDR: 5300 NW 12 AV # 7

OWNER: D'ANNUNZIO, FRANK & D'ANNUNZIO, VICTORIA

INSPECTOR: IVETT SPENCE-BROWN

REQUEST FOR EXTENSION OF TIME

VIOLATIONS: NFPA 101 4.5.5

2ND FLOOR HAS UNENCLOSED UNPROTECTED VERTICAL OPENING THAT EXITS IN THE WAREHOUSE. ADDITIONALLY, 2ND FLOOR OFFICES HAVE UNENCLOSED VERTICAL OPENING THAT DISCHARGES IN THE

LOBBY.

NFPA 101 7.2.1.8.1

THE SELF-CLOSING DEVICE IS MISSING FROM THE FIRE DOOR ON THE

2ND FLOOR.

\_\_\_\_\_\_

HEARING COMPUTER SCHEDULED

\_\_\_\_\_\_

CASE NO: CE03050743 CASE ADDR: 726 NW 57 ST

OWNER: SOUTHBOUND INVESTMENTS INC

INSPECTOR: IVETT SPENCE-BROWN

VIOLATIONS: NFPA 1 1-4.4

UNABLE TO GAIN ACCES FOR FIRE INSPECTION.

\_\_\_\_\_\_

CASE NO: CE03050746
CASE ADDR: 5913 NW 31 AVE
OWNER: LAKEVIEW PLAZA INC
INSPECTOR: IVETT SPENCE-BROWN

VIOLATIONS: NFPA 101 39.2.4.2

SECOND FLOOR DOES NOT HAVE LEGAL EXITING.

NFPA 101 39.3.1.1

BUILDING HAS UNENCLOSED, UNPROTECTED VERTICAL OPENING.

-----

CASE NO: CE03050744 CASE ADDR: 1139 NE 10 AV

OWNER: KERN, RONRICK H & SUSAN J

INSPECTOR: JEFF LUCAS

VIOLATIONS: NFPA 1 1-4.4

ADDRESS IS NOT VISIBLE.

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM

JUNE 24, 2003 10:00 AM

\_\_\_\_\_\_

CASE NO: CE03050745 CASE ADDR: 1021 NE 8 AV

OWNER: B & B INVESTMENTS INTL LC

INSPECTOR: JEFF LUCAS

VIOLATIONS: NFPA 1 1-4.4

EXISTING RAILING BY #60 IS BROKEN AND IN NEED OF REPAIR.

-----

CASE NO: CE03060710
CASE ADDR: 1115 NE 9 AVE
OWNER: RUST, JACK R TR
INSPECTOR: JEFF LUCAS

VIOLATIONS: NFPA 101 39.2.4.1

SECOND FLOOR OFFICE HAS ONLY ONE INTERIOR STAIR.

NFPA 101 42.2.9

EMERGENCY LIGHTS DO NOT EXIST.

NFPA 101 42.2.10

EXIT SIGNS DO NOT EXIST.

FBC 104.1

SECOND FLOOR STORAGE AREA, OFFICE AND FIRST FLOOR OFFICES

HAVE BEEN CONSTRUCTED WITHOUT A PERMIT.

-----

CASE NO: CE03060730 CASE ADDR: 1125 NE 9 AVE

OWNER: RUST, JACK TR 1 DK TRUST #1

INSPECTOR: JEFF LUCAS

VIOLATIONS: NFPA 1 17-3.7.1

SPRAY AREAS LACK A FIRE SUPPRESSION SYSTEM.

-----

RETURN HEARING (OLD BUSINESS)

-----

CASE NO: CE00101168
CASE ADDR: 125 NW 4 ST
OWNER: -FLAGLER 400 LLC

OWNER: -FLAGLER 400 LLC REQUEST FOR ABATEMENT OF FINES

INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: 301(a) Complied

ALTERED THE INTERIOR BY ERECTING NEW WALLS, REROOFED OVER THE DOORS WITH CORRUGATED METAL, SEALED AND PAINTED THE LARGER ROOFS, RE-SEALED THE PARKING LOT, ALL WITHOUT PERMITS

OR INSPECTIONS.

304.3(a) **Complied** 

INSTALLED CENTRAL AC UNIT IN THE OFFICE WITH PERMIT 99082068

ISSUED ON 9/17/1998 WITH NO INSPECTIONS, THE PERMIT HAS

EXPIRED, THUS THE PERMIT IS NULL AND VOID.

47-20.4 D.1. **Complied** 

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM JUNE 24, 2003 10:00 AM

THERE IS NO HANDICAPPED PARKING SPACES, AS PER SECTIONS 316.1955, 316.1956, AND 553.48 FLORIDA STATUTES AND FLORIDA ACCESS CODE.

#### 47-20.8 Complied

THERE IS NO PAVEMENT MARKINGS FOR PARKING AT THIS OFFICE.

#### 47-21.3 **Complied**

THERE IS NO LANDSCAPING ON THIS OFFICE SITE.

#### 47-21.9 G.1. Complied

THERE IS NO RETROACTIVE LANDSCAPING ON THIS SITE.

#### FAC 4.1.6(3)(a) **Complied**

THE BUILDING DOES NOT MEET THE A.D.A REQUIREMENTS FOR HANDICAPPED ACCESSIBILITY.

#### FAC 4.6.4 Complied

THERE IS NO HANDICAPPED ACCESSIBLE PARKING SIGNAGE ON THIS SITE.

\_\_\_\_\_\_

CE01060446 CASE NO:

CASE ADDR: 1706 S FEDERAL HWY REQUEST FOR ABATEMENT

WILLIAMSON, ROBERT INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: 301(a) Complied

THEY HAVE INSTALLED NEW SIGNS AT MIAMI SUBS WITHOUT A

PERMIT.

CASE NO: CE01110773

REQUEST FOR EXTENSION OF TIME

CASE ADDR: 2216 S FEDERAL HWY
OWNER: SULTAN FAMILY LTD PRTNR
INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: 301(a)

THE NORTH PORTION OF THE BUILDING HAS BEEN COMPLETELY GUTTED AND CONVERTED INTO A BOAT REPAIR SHOP. THE EXTERIOR MASONARY WALL WAS ALTERED BY CREATING AN OPENING FOR A FUTURE WAREHOUSE TYPE R OVERHEAD DOOR. THIS WORK WAS DONE WITHOUT

FIRST OBTAINING A PERMIT.

301.1(k)

A NEW A/C UNIT HAS BEEN INSTALLED WITHOUT OBTAINING A MECHANICAL PERMIT.

503.2

THE USE OF THIS SPACE HAS BEEN FROM AN ASSEMBLY USE TO A BOAT REPAIR/STORAGE USE WITHOUT A PERMIT AND A CERTIFICATE OF OCCUPANCY.

CODE ENFORCEMENT BOARD
CITY COMMISSION MEETING ROOM
JUNE 24, 2003

10:00 AM

\_\_\_\_\_\_

CASE NO: CE02010698 CASE ADDR: 1448 NW 6 ST

OWNER: SIXTH STREET CORP REQUEST FOR ABATEMENT OF FINES

OWNER: SIXTH STREET CORP INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1 Complied

FRAMED OUT ARCHWAYS , INSTALLED A DOOR, COVERED THE ARCHWAYS WITH DIAMOND MESH AND STUCCO, AND GOING BEYOND THE SCOPE OF

RAFTER REPAIR PERMIT, ALL WITHOUT PERMITS.

FBC 104.2.4 Complied

INSTALLED A WATER HEATER AND PLUMBING WITHOUT A PERMIT.

FBC 104.2.5 Complied

INSTALLED AND ALTERED ELECTRICAL WITHOUT PERMITS.

FBC 104.9.3.1 **Complied** 

THE PERMIT TO REPAIR THE FLOOR JOISTS #01121564 ISSUED ON 1/15/2002, HAD A JOB CHECK WHICH WAS PASSED ON 1/23/2002 WITH NO FURTHER INSPECTION HAS BECOME NULL AND VOID.

-----

CASE NO: CE02101898
CASE ADDR: 5 PELICAN DR

OWNER: CARSON, JAMES T & CARSON, ROXANNE N

INSPECTOR: ROBERT A PIGNATARO

REQUEST FOR EXTENSION OF TIME

VIOLATIONS: FBC 104.9.3.1

THE POOL PERMIT # 01061502 ISSUED ON 7/10/2001 FOR A POOL AND SPA HAS NOT PASSED AN INSPECTION SINCE 10/1/2001, THUS

IS NULL AND VOID.

47-19.5.E.

BUILT A WATER FALL NEXT TO THE POOL THAT IS NOT ON THE POOL

PLANS AND IS TOO HIGH.

\_\_\_\_\_

CASE NO: CE03021409
CASE ADDR: 1045 NE 18 AVE

OWNER: BOEMERMANN, RICHARD J REQUEST FOR EXTENSION OF TIME

INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: 47-21.1.A.

THE LANDSCAPING AND GRASS IS NOT BEING MAINTAINED PER THE CITY OF FORT LAUDERDALE'S MINIMUM HOUSING CODE OR ULDR.

9-304.(b)

THE PARKING LOTS HAVE NOT BEEN MAINTAINED. THERE ARE HOLES IN THE ASPHALT AND THE PARKING LOTS NEED TO BE REPAINTED AND

RESTRIPED.

9-306

THE RAILINGS ON THE TWO STORY BUILDING FROM THE GROUND LEVEL TO THE SECOND FLOOR AND THE RAILINGS ON THE SECOND FLOOR ARE LOOSE AND IN DISREPAIR.

9-307(a)

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM JUNE 24, 2003 10:00 AM

SEVERAL OF THE JALOUSIE WINDOWS ARE BROKEN AND/OR IN DISREPAIR. THERE ARE SCREENS MISSING FROM SEVERAL WINDOWS.

FBC 104.2.11

INSTALLED WINDOW AIR CONDITIONER UNITS WITHOUT A PERMIT.

FBC 104.2.5

INSTALLED EXTERIOR LIGHTING AND WIRING WITHOUT PERMIT AND NOT PER CODE.

FBC 3401.6

THE BUILDINGS HAVE NOT BEEN MAINTAINED ACCORDING TO THE CITY OF FORT LAUDERDALE MINIMUM HOUSING CODE AND THE FLORIDA BUILDING CODE, INCLUDING, BUT NOT LIMITED TO:

- 1. THE CEILING IN THE ROOM WITH THE WATER HEATER THAT HAS HOLES IN IT AND PARTS OF THE CEILING HAVE BEEN REPLACED AND NOT PER CODE.
- 2. THERE IS A TOILET IN THE ROOM WITH THE WATER HEATER THAT IS NOT WORKING.

\_\_\_\_\_\_

CASE NO: CE99051743 CASE ADDR: 824 NW 16 AV OWNER: EVANS, JOHNY DEAN INSPECTOR: ROBERT A PIGNATARO

REQUEST FOR EXTENSION OF TIME

VIOLATIONS: 105.1(a)

THERE ARE INOPERABLE WINDOWS AND SCREENS MISSING. THE FRONT PORCH POST IS ROTTING AND THE PORCH IS IN DANGER OF COLLAPSING. NORTH SIDE OF ROOF HAS TERMITE DAMAGE.

301(a)

REAR PATIO ALUMINUM AWNING, SLAB AND WALLS WERE INSTALLED WITHOUT FIRST OBTAINING THE REQUIRED PERMIT. SLAB IS CRACKED AND WALLS ARE SINKING.

HEARING COMPUTER SCHEDULED

CASE NO: CE03051135

CASE ADDR: 624 ORTON AV # 18

OWNER: STEWART, ANTHONY & JUDITH PRYCE

INSPECTOR: ROBERT KISAREWICH

VIOLATIONS: NFPA 101 31.2.1

THERE ARE SECURITY BARS ON THE BEDROOM WINDOW THAT PROHIBIT

THE USE OF THE WINDOW AS A MEANS OF ESCAPE.

CASE NO: CE03051136 CASE ADDR: 538 BAYSHORE DR

OWNER: JENKINS, GEORGE ROBERT INSPECTOR: ROBERT KISAREWICH

VIOLATIONS: FBC 104.1

CITY OF FORT LAUDERDALE AGENDA

### CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM JUNE 24, 2003

10:00 AM

A NEW FIRE ALARM SYSTEM WAS INSTALLED WITHOUT FIRST OBTAINING A PERMIT.

CASE NO: CE03051137 CASE ADDR: 501 N BIRCH RD

OWNER: MAGNA CASA DEV II LLC INSPECTOR: ROBERT KISAREWICH

VIOLATIONS: FBC 104.1

CONVERTED APARTMENT #1 AND #5 TO A SALES OFFICE WITHOUT

FIRST OBTAINING PERMITS.

NFPA 1 1-4.5

THERE IS STORAGE IN THE ELECTRIC METER ROOM.

\_\_\_\_\_\_

CE03051138 CASE NO: CASE ADDR: 519 N BIRCH RD

OWNER: MAGNA CASA DEV II LLC INSPECTOR: ROBERT KISAREWICH

VIOLATIONS: NFPA 1 3-7.1

THE BUILDING ADDRESS IS NOT VISIBLE FROM THE STREET.

NFPA 1 4-7.2

THE EMERGENCY LIGHTS ARE NOT OPERABLE.

NFPA 1 4-8.5.2

THE EXIT SIGNS ARE NOT OPERABLE.

CASE NO: CE03060354

CASE ADDR: 121 HENDRICKS ISLE

OWNER: VELGER, EARL R & VELGER, VIRGINIA L

INSPECTOR: ROBERT KISAREWICH

VIOLATIONS: BCA FFPC F-20.3

A FIRE LINE IS NOT PROVIDED FOR THE DOCKAGE OF FOUR VESSELS.

FBC 104.9.3.1

PERMIT #02031397 TO INSTALL THE REQUIRED FIRE LINE HAS BECOME INVALID SINCE 180 DAYS HAVE PAST AND NO WORK HAS

COMMENCED.

\_\_\_\_\_\_

CE03060360 CASE NO:

CASE ADDR: 211 S FT LAUD BEACH BLVD OWNER: MINIACI ENTERPRISES INSPECTOR: ROBERT KISAREWICH

VIOLATIONS: FBC 104.1

AN OFFICE HAS BEEN CONSTRUCTED IN THE BASEMENT WITHOUT FIRST

OBTAINING PERMITS.

#### CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM JUNE 24, 2003

10:00 AM

\_\_\_\_\_\_

CASE NO: CE03060497

CASE ADDR: 2933 POINSETTIA ST

OWNER: GATOR EAST WIND PARTNERS LLLP INSPECTOR: ROBERT KISAREWICH

VIOLATIONS: FBC 104.1

THE FOURTH FLOOR ELEVATOR LOBBY HAS BEEN ENCLOSED TO LIVING

AREA (APARTMENT 40) WITHOUT FIRST OBTAINING A PERMIT.

NFPA 101 31.2.9

THERE IS NO EMERGENCY LIGHTING ALONG THE PATH OF EGRESS ON

THE 2ND AND 3RD FLOORS.

NFPA 101 31.3.4.1

THE BUILDING IS NOW FOUR FLOORS OF OCCUPIED AREA AND

REQUIRES A FIRE ALARM SYSTEM.

NFPA 101 7.2.1.8.1

THE SELF-CLOSERS ON THE STAIRWELL DOORS ARE NOT PROPERLY

ADJUSTED AND/OR ARE BROKEN.

NFPA 82 3-2.2.9

THE BASE OPENING OF THE TRASH CHUTE IS NOT PROTECTED WITH AN

APPROVED AUTOMATIC SELF-CLOSING DEVICE.

NFPA 82 3-2.4.1

THE CHUTE LOADING DOORS INTO THE WASTE CHUTE ARE NOT SELF-

CLOSING WITH A POSITIVE LATCH.

RETURN HEARING (OLD BUSINESS)

CASE NO: CE98100824

CASE ADDR: 1147 NE 04 AV
OWNER: LAUDERDALE WHOLESALE INC REQUEST FOR EXTENSION OF TIME

INSPECTOR: MOHAMMED MALIK

VIOLATIONS: 301(a) Complied

INSTALLED CHAIN LINK FENCE, AND INTERIOR WALL WITHOUT FIRST

OBTAINING A BUILDING PERMIT.

301.1(d) Complied

INSTALLED SLOP SINK ON EXTERIOR, REMOVED TOILET WITHOUT

FIRST OBTAINING PLUMBING PERMIT.

301.1(e) Complied

INSTALLED TWO WALL AIR CONDITIONER UNITS, INSTALLED ELECTRIC TO COOLER IN GARAGE WITHOUT FIRST OBTAINING AN ELECTRICAL

PERMIT.

301.1(k) Complied

INSTALLED TWO WALL AIR CONDITIONER UNITS WITHOUT FIRST

OBTAINING A MECHANICAL PERMIT.

47-25.3.C.4.d **Complied** 

MUST HAVE BUFFER WALL BETWEEN COMMERCIAL AND RESIDENTIAL

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM JUNE 24, 2003 10:00 AM

PROPERTIES.

#### 47-3.4 Complied

CHANGE OF USE FROM A SERVICE STATION TO A FLORIST SHOP WITHOUT FIRST SUBMITTING FOR A CHANGE OF USE.

\_\_\_\_\_\_

CASE NO: CE99110073 CASE ADDR: 901 NE 3 ST

OWNER: JOVOVICH RENTAL PROPERTY REQUEST FOR ABATEMENT OF FINES

INSPECTOR: MOHAMMED MALIK

VIOLATIONS: 301(a) Complied

INSTALLED WOOD FENCE AND POSTS WITHOUT FIRST OBTAINING A

BUILDING PERMIT.

301.1(d) Complied

INSTALLED PLUMBING FOR HOSE BIBS WITHOUT FIRST OBTAINING

A PLUMBING PERMIT.

\_\_\_\_\_\_

HEARING COMPUTER SCHEDULED

\_\_\_\_\_\_

CASE NO: CE01100240 CASE ADDR: 631 NE 18 AV

STORELLI, JOHN & SUSAN

INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 104.1

ENCLOSED CARPORT WITHOUT OBTAINING REQUIRED PERMITS.

NOTE: BOARD OF ADJUSTMENT CASE NO 01-47 APPEAL DENIED PERMIT APPLICATION A-0105283 FAILED ZONING.

\_\_\_\_\_\_

CASE NO: CE02091424

CASE ADDR: 729 N VICTORIA PARK RD OWNER: JARRETT, EDMOND THORNTON

INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PER-MIT, THIS INCLUDES, BUT IS NOT LIMITED TO:

- 1. INSTALLATION OF NEW ROOF
- 2. INSTALLED NEW (REPLACED) DOORS
- 3. INSTALLED NEW (REPLACED) WINDOWS 4. NEW STUCCO
- 5. NEW BLOCK WALLS

#### FBC 3401.6

THE FOLLOWING ITEMS REQUIRE MAINTENANCE:

- 1. BROKEN WINDOW GLASS
- 2. EXPOSED ELECTRICAL WIRING
- 3. MISSING LIGHT FIXTURES

CODE ENFORCEMENT BOARD
CITY COMMISSION MEETING ROOM
JUNE 24, 2003
10:00 AM

24-11(a)

CONSTRUCTION DEBRIS IS STORED IN YARD WITHOUT A CONTAINER

24-11 (d)

CONSTRUCTION DEBRIS IS STORED IN YARD WITHOUT A CONTAINER FOR MORE THAN THREE (3) MONTHS.

47-21.8 A.

LANDSCAPING IS NOT MAINTAINED, WEEDS, DEAD SOD, ETC.

9-306

EXTERIOR WALL NOT BEING MAINTAINED, CHISEL MARKS (HOLES IN STUCCO).

\_\_\_\_\_

CASE NO: CE02102367
CASE ADDR: 4210 NE 29 AVE
OWNER: ISRAEL, DOV VICTOR
INSPECTOR: MOHAMMED MALIK

VIOLATIONS: 9-313

PREMISES IDENTIFICATION NUMBER IS NOT VISIBLE FROM STREET OR ROAD FRONTING THE PROPERTY.

FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMIT. THIS INCLUDES:

- INSTALLED WOOD FENCE. (APPLIED FOR PERMIT #02110415, NEVER OBTAINED)
- 2. INSTALLED BRICK PAVERS (APPLIED FOR PERMIT #02110416, NEVER OBTAINED)

-----

CASE NO: CE02121287

CASE ADDR: 125 E SUNRISE BLVD
OWNER: FINANCIAL FINANCE LTD

INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 3108.1.3.1

INSTALLED SIGN WITHOUT FIRST OBTAINING REQUIRED PERMITS.

-----

CASE NO: CE03031355 CASE ADDR: 6351 NE 20 TER

OWNER: GUILLEN, O M & BLANCA C

INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENT TO THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMIT, THIS INCLUDES, BUT IS NOT LIMITED TO:

- 1. COLUMN POST AND ROOF ADDED ON THE REAR OF THE PROPERTY WITHOUT FIRST OBTAINING PERMITS.
- 2. INSTALLED FENCE.

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM JUNE 24, 2003 10:00 AM

#### FBC 3401.6

THE FOLLOWING ITEMS REQUIRE MAINTENANCE:

- 1. ROOF FASCIA ROTTED, NEED TO BE REPLACED
- 2. DOCK IN DISREPAIR, NEED TO REPAIR/REPLACE
- STRUCTURAL COLUMN AND POST ARE DAMAGE/ROTTED WOOD, ON THE FRONT PORCH NEED REPAIR/REPLACE
- 4. SOFFIT ON THE WEST SIDE IS SAGGING AND BRACED WITH METAL ANGLES, NEED ENGINEER DRAWINGS AND PERMIT.

\_\_\_\_\_\_

CASE NO: CE03031941 CASE ADDR: 980 NW 10 AVE

OWNER: DADAN PACKAGING INC INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 11-4.6.4

THE REQUIRED HANDICAP SIGNAGE FOR THE EXISTING BUILDING IS NOT IN COMPLIANCE WITH CODE.

15 - 28

ENGAGING IN BUSINESS WITHOUT FIRST OBTAINING AN OCCUPATIONAL LICENSE TO DO SO.

#### FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENT TO THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMIT TO INCLUDE:

- 1. ADDITION OF NEW OFFICE, TWO FLOORS, WHICH INCLUDES STRUCTURAL, ELECTRICAL, PLUMBING AND MECHANICAL WORK.
- 2. NEW EXTERIOR DOOR ADDED
- 3. NEW EXTERIOR SHUTTER DOOR
- 4. CHAIN LINK FENCE ADDED (NOTE: APPLIED FOR PERMIT #02121543, FAILED ZONING, NEVER OBTAINED PERMIT).
- 5. ADDED NEW SIDEWALK IN FRONT OF NEW EXTERIOR DOOR.

#### FBC 104.2.4

BUILT NEW BATHROOM WITHOUT FIRST OBTAINING REQUIRED PERMITS.

### FBC 104.2.5

NEW ELECTRICAL WORK IN TWO-STORY OFFICE WITHOUT FIRST OBTAINING REQUIRED PERMITS.

#### 47-20 20 H

PARKING LOT NEEDS RE-STRIPPING.

#### FBC 11-4.6.1

THE REQUIRED HANDICAP PARKING FOR THE EXISTING BUILDING IS NOT IN COMPLIANCE WITH CODE.

CODE ENFORCEMENT BOARD
CITY COMMISSION MEETING ROOM
JUNE 24, 2003
10:00 AM

------

CASE NO: CE03040808

CASE ADDR: 45 FORT ROYAL ISLE OWNER: DUNN-SHAMY, JANINE INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING

PERMIT, THIS INCLUDES:

1. ADDED NEW EXTERIOR BAY WINDOW

FBC 104.2.4

RENOVATED BATHROOM WITHOUT FIRST OBTAINING REQUIRED PERMITS.

FBC 104.2.5

ELECTRICAL WORK WITHOUT FIRST OBTAINING REQUIRED PERMITS.

-----

RETURN HEARING (OLD BUSINESS)

-----

CASE NO: CE02060922 CASE ADDR: 632 SW 4 AVE

OWNER: FELL, JAMES R & LILLIAN C REQUEST FOR EXTENSION OF TIME

INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

THE REAR APARTMENT OF THIS DUPLEX HAS BEEN CONVERTED INTO AN OFFICE WITHOUT FIRST OBTAINING A BUILDING PERMIT. A PERMIT WAS ISSUED IN 1987 TO CONVERT THE FRONT APARTMENT TO A LAW OFFICE, BUT THE REAR APARTMENT WAS NOT INCLUDED IN THIS

PERMIT.

FBC 11-4.1.2(5)(a)

THERE IS NO HANDICAP PARKING AT THIS OFFICE BUILDING.

FBC 106.1

THE REAR OFFICE OF THIS BUILDING IS BEING OCCUPIED AS AN OFFICE WITHOUT FIRST OBTAINING A CERTIFICATE OF OCCUPANCY FROM THE BUILDING OFFICIAL.

15-28

THE AUDIO VIDEO INTELLIGENCE BUSINESS IS OPERATING AT THIS LOCATION IWTHOUT AN OCCUPATIONAL LICENSE.

-----

CASE NO: CE02091696
CASE ADDR: 1016 GUAVA ISLE
OWNER: CIAVATTO, JASON E
INSPECTOR: KENNETH REARDON

REQUEST FOR ABATEMENT OF FINES

VIOLATIONS: FBC 104.9.3.1 Complied

PERMIT 00051724 FOR AFTER-THE-FACT REPLACEMENT OF WINDOWS AND ADDING GLASS BLOCK, HAS EXPIRED SINCE NO PASSING INSPECTION WAS OBTAINED IN OVER 90 DAYS.

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM JUNE 24, 2003

10:00 AM

\_\_\_\_\_\_

CASE NO: CE02100344 CASE ADDR: 1430 SW 34 TER

REQUEST FOR EXTENSION OF TIME

OWNER: STEWART, NORMAN INSPECTOR: KENNETH REARDON

VIOLATIONS: 9-280(q)

THE EXTERIOR ELECTRICAL IS NOT MAINTAINED AND THERE IS

LOOSE AND EXPOSED WIRED AND FIXTURES.

#### 9-281(b) **Complied**

THE YARD IS NOT BEING MAINTAINED. THE GRASS IS OVERGROWN IN AREAS AND MISSING IN OTHER AREAS. THERE IS TRASH, RUBBISH AND DEBRIS THROUGHOUT THE YARD, INCLUDING, BUT NOT LIMITED TO THE FOLLOWING:

1-AN OLD AIR CONDITIONING UNIT

2-AN OLD GAS FURNACE

3-OLD PVC PIPING

4-ABANDONED FENCING

5-OLD AIR CONDITIONING FREON GAS LINES

6-BROKEN UP CONCRETE

7-AN OLD TOILET

8-FRONT YARD SAND PILE

#### FBC 104.1

THE FOLLOWING WORK HAS BEEN DONE WITHOUT FIRST OBTAINING A BUILDING PERMIT

- 1- THE BUILDING HAS BEEN REROOFED.
- 2- INTERIOR DRYWALL WORK
- 3- KITCHEN AND BATHROOM CABINETS HAVE BEEN REMOVED
- 4- WINDOW REPLACEMENT
- 5- EXTERIOR STUCCO WORK

#### FBC 104.2.4

THE DEMOLITION OF THE KITCHEN, BATHROOM AND WATER HEATER PLUMBING WITHOUT FIRST OBTAINING A PLUMBING PERMIT.

#### FBC 104.2.5

THE INTERIOR ELECTRIC FIXTURES HAVE BEEN REMOVED AND CIRCUITS ADDED TO THE REAR AND SOUTH EXTERIOR WALLS WITHOUT FIRST OBTAINING AN ELECTRICAL PERMIT.

#### FBC 3401.6

THERE ARE LARGE STRUCTURAL CRACKS ON T5HE NORTH AND EAST EXTERIOR WALLS.

CASE NO: CE02110605 CASE ADDR: 812 SW 11 AVE OWNER: HUGUES, FRED G INSPECTOR: KENNETH REARDON

REQUEST FOR EXTENSION OF TIME

VIOLATIONS: FBC 104.1

THE FOLLOWING WORK HAS BEEN DONE WITHOUT FIRST OBTAINING A

BUILDING PERMIT:

### CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM JUNE 24, 2003 10:00 AM

- A. THE SOUTHEAST PORCH HAS BEEN ENCLOSED
- B. A SLIDING GLASS DOOR HAS BEEN ADDED TO THE SOUTH WALL
- C. THE NORTH WALL EAST WINDOW HAS BEEN REPLACED AND THE OPENING WAS ALTERED
- D. THE KITCHEN HAS BEEN REMODELED
- E. A LARGE WOOD SHED/GARAGE HAS BEEN ADDED

#### FBC 104.2.4

THE KITCHEN SINK HAS BEEN REPLACED WITHOUT FIRST OBTAINING A PLUMBING PERMIT.

#### FBC 104.2.5

A NEW OUTLET HAS BEEN ADDED TO THE SOUTH EXTERIOR WALL, A NEW CENTRAL AIR CONDITIONING SYSTEM WIRED AND THE KITCHEN REMODELED WITHOUT FIRST OBTAINING AN ELECTRICAL PERMIT.

#### FBC 104.2.11

A CENTRAL AIR CONDITIONING SYSTEM WAS INSTALLED IN 1993 WITHOUT FIRST OBTAINING A MECHANICAL PERMIT.

#### FBC 104.9.3.1

THE FOLLOWING PERMITS HAVE EXPIRED SINCE NO PASSING IN-SPECTIONS WERE OBTAINED IN OVER 90 DAYS:

- A. 02080513 FOR WOOD FENCE
- B. 10162257 FOR WATER SERVICE
- C. 99062254 FOR THE POOL DECK
- D. 99040484 FOR NEW POOL
- E. 99040486 FOR POOL ELECTRIC

\_\_\_\_\_\_

CASE NO: CE02120718

CASE ADDR: 3232 SW 2 AV # 103

OWNER: SMITH, STEVEN M
INSPECTOR: KENNETH REARDON REQUEST FOR ABATEMENT OF FINES

#### VIOLATIONS: FBC 104.2.11 Complied

A CENTRAL AIR CONDITIONING SYSTEM WAS ADDED TO THIS WARE-HOUSE BAY WITHOUT FIRST OBTAINING A MECHANICAL PERMIT.

#### FBC 104.1 Complied

A LOFT AND SECOND FLOOR OFFICES WERE BUILT WITHOUT FIRST OBTAINING A BUILDING PERMIT.

# FBC 104.2.5 Complied

ELECTRICAL WIRING HAS BEEN ADDED TO THE LOFT, UNDER THE LOFT, IN THE UPPER OFFICES AND THE CONNECTIONS TO THE CENTRAL AIR CONDITIONER; ALL WITHOUT FIRST OBTAINING AN ELECTRICAL PERMIT,

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM JUNE 24, 2003

10:00 AM

\_\_\_\_\_\_

CASE NO: CE02021280
CASE ADDR: 204 SW 21 TER
OWNER: SAHAGIAN, GEORGE TR
INSPECTOR: KENNETH REARDON

VIOLATIONS: 18-27(a)

THERE IS TRASH, RUBBISH AND DEBRIS ON THE PROPERTY IN-CLUDING, BUT NOT LIMITED TO OLD FURNITURE AND A DERELICT MERCEDES BENZ INSIDE THE FENCED AREA.

9 - 304 (b)

THE PARKING LOT IS NOT BEING MAINTAINED.

9 - 305 (b)

THE LANDSCAPE IS NOT BEING MAINTAINED AND THERE IS AN ACCUMULATION OF REFUSE AND DEBRIS ON THE PROPERTY.

9-306

THERE ARE HOLES IN THE REAR EXTERIOR WALL. THE BUILDING PAINT IS NOT BEING MAINTAINED.

9-307(a)

THERE ARE BROKEN WINDOWS.

FBC 104.1

THE FRONT AND REAR EXTERIOR WALL OPENINGS AND LOADING DOCKS HAVE BEEN DEMOLISHED AND NEW OVERHEAD DOORS INSTALLED. ALSO A NEW DOOR AND STAIRWAY HAVE BEEN ADDED AT THE NORTHWEST CORNER. THIS HAS ALL BEEN DONE WITHOUT FIRST OBTAINING A BUILDING PERMIT.

FBC 104.9.3.1

PERMIT 01020404 FOR THE CHANGE OF USE, PERMIT 01030064 FOR IN GROUND PITS FOR NEW SPRAY BOOTHS AND MIX ROOM, AND PERMIT 02030067 FOR DRY CHEMICAL FIRE SYSTEM FOR NEW SPRAY BOOTHS HAVE EXPIRED SINCE NO PASSING INSPECTIONS WERE OBTAINED IN OVER 90 DAYS.

FBC 3401.6

THERE IS AN ELECTRICAL CONDUIT PIPE WITH EXPOSED WIRES HANGING OFF THE ROOF AT THE REAR WALL OF THE BUILDING.

\_\_\_\_\_\_

CASE NO: CE02051589
CASE ADDR: 407 SW 22 AV
OWNER: TAYLOR, WILLIE GENE

OWNER: TAYLOR, WILLIE GENE INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.9.3.1

PERMIT #02022365 FOR AFTER-THE-FACT PAVED DRIVEWAY,

#02020449 FOR AFTER-THE-FACT FOUR (4) WINDOWS, GLASS BLOCK AND DOOR, AND #02021262 FOR AFTER-THE-FACT WOOD FENCE HAVE EXPIRED SINCE NO PASSING INSPECTIONS WERE OBTAINED IN OVER

90 DAYS.

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM JUNE 24, 2003

10:00 AM

\_\_\_\_\_\_

CASE NO: CE03011008 CASE ADDR: 3101 SW 13 ST

OWNER: SCULLY, JOSEPH L & LINDA INSPECTOR: KENNETH REARDON

VIOLATIONS: 9-279(f)

THE WASHING MACHINE WASTE LINE DRAINS TO THE YARD.

9-280 (b)

THERE ARE BROKEN WINDOWS AND MISSING AND TORN SCREENS. THE HALF FINISHED REPAIRS TO THE CEILINGS MUST BE COMPLETED.

9-280(q)

THERE IS A FLORESCENT LIGHT FIXTURE ON THE CARPORT, WHICH HAS BEEN DISCONNECTED AND SHOULD BE REMOVED.

9-281(b)

THERE IS TRASH, RUBBISH AND DEBRIS IN THE YARD INCLUDING, BUT NOT LIMITED TO REROOF TEAR OFF, OLD FENCING AND FENCE POSTS, ABANDONED CAR PARTS AND AN UNLICENSED TRAILER.

9-305(b)

THERE IS MISSING GROUND COVER AND AREAS OF OVERGROWTH.

THE BUILDING PAINT IS NOT BEING MAINTAINED.

FBC 104.1

THE FRONT PORCH HAS BEEN ENCLOSED INTO A ROOM WITHOUT FIRST OBTAINING A BUILDING PERMIT.

CASE NO: CE03011855
CASE ADDR: 3029 CENTER AV
OWNER: DAKAK, WILLIAM A INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.2.4

NEW SINKS AND TOILETS HAVE BEEN INSTALLED IN THE SOUTHWEST, SOUTHEAST AND NORTHEAST BEDROOM BATHS WITHOUT FIRST OB-TAINING A PLUMBING PERMIT.

9-279(f)

THE WASH MACHINE WASTE LINE IS CONNECTED TO HOSE THAT RUNS OUT THE WINDOW AND DISCHARGES INTO THE GROUND.

9-313(a)

THE HOUSE NUMBERS ARE PAINTED OVER AND DO NOT CONTRAST WITH THEIR BACKGROUND.

CASE NO: CE03020870 CASE ADDR: 1340 SW 35 AV

LOUIE, CORRINA Y TR, RIEWE, STEPHEN M

INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM JUNE 24, 2003 10:00 AM

THE FOLLOWING WORK WAS DONE WITHOUT FIRST OBTAINING A BUILDING PERMIT:

- 1. CUT THE TIE BEAM AND REPLACED A DOOR AT THE SOUTH SIDE OF THE CENTER BREEZEWAY.
- 2. APARTMENT A4 HAS BEEN ILLEGALLY CONVERTED INTO TWO (2) LIVING UNITS (A4 & A4A).
- 3. THE FRONT AND REAR WALLS HAVE BEEN OPENED TO ACCOM-MODATE WALL AIR CONDITIONING UNITS IN APARTMENTS A4 AND A4A.

#### FBC 104.2.4

PLUMBING LINES HAVE BEEN ADDED TO THE REAR EXTERIOR WALL AND THE EXTERIOR WALL OF THE CENTER BREEZEWAY WITHOUT FIRST OBTAINING A PLUMBING PERMIT.

#### FBC 104.2.5

ELECTRICAL LINES HAVE BEEN ADDED TO THE REAR EXTERIOR WALL, THE EXTERIOR WALL OF THE CENTER BREEZEWAY AND TO THE WALL AIR CONDITIONING UNITS IN APARTMENT A4 AND A4A WITHOUT FIRST OBTAINING AN ELECTRICAL PERMIT.

#### FBC 104.2.11

WALL AIR CONDITIONING UNITS HAVE BEEN ADDED TO APARTMENTS A4 AND A4A WITHOUT FIRST OBTAINING A MECHANICAL PERMIT.

#### 9-279(f)

A PLUMBING WASTE LINE DISCHARGES TO THE GROUND AT THE REAR EXTERIOR WALL, JUST NORTH OF THE CENTER BREEZEWAY.

#### 9-280(f)

THERE IS A MISSING ROOF DRAIN PIPE AT THE NORTH END OF THE REAR WALL OF THE BUILDING, WHICH SHOULD BE REPLACED.

#### 9-280(h)(1)

THE POOL WOOD AND CHAIN LINK FENCES ARE DAMAGED AND ARE NOT BEING MAINTAINED.

#### 9-280(b)

THE RAIN GUTTERS ARE RUSTED AND DAMAGED. THERE ARE MISSING WINDOW SCREENS THROUGHOUT THE BUILDING. THE DOOR, DOOR FRAME AND WALL ARE ROTTED AT THE STORAGE AREA UNDER THE NORTH STAIRWAY.

#### 9-304(b)

THE PARKING LOT HAS POTHOLES AND IS NOT BEING MAINTAINED TO THE MINIMUM STANDARDS OF THIS CODE.

#### FBC 3401.6

THERE ARE STORED ITEMS IN THE METER ROOM. THIS IS NOT SAFE AND IS NOT ALLOWED.

#### 9-305(b)

THERE IS MISSING GRASS AT THE SOUTHWEST CORNER OF THE BUILDING.

#### 47-19.4 D.8.

THE DUMPSTER ENCLOSURE FENCE WALLS ARE DAMAGED AND REQUIRE

#### CITY OF FORT LAUDERDALE

AGENDA

CODE ENFORCEMENT BOARD
CITY COMMISSION MEETING ROOM
JUNE 24, 2003
10:00 AM

REPAIR.

\_\_\_\_\_\_

CASE NO: CE03030189
CASE ADDR: 2869 SW 13 CT
OWNER: SMITH, MARILYN
INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

WOOD STRUCTURES HAVE BEEN CONSTRUCTED AT THE EAST SIDE OF THE BUILDING AND OVER THE DRIVEWAY AND FRONT ENTRANCE TO THE

HOUSE WITHOUT FIRST OBTAINING A BUILDING PERMIT.

-----

CASE NO: CE03031063 CASE ADDR: 3700 SW 16 ST

OWNER: LEMUS, JOSE I & LEMUS, MARIA C, ET AL

INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

INSTALLED A NEW PAVER DRIVEWAY WITHOUT FIRST OBTAINING A

BUILDING PERMIT.

\_\_\_\_\_\_

CASE NO: CE03040189 CASE ADDR: 713 SW 22 AV

OWNER: WATSON, JOANN & SWAN, JOE MARY

INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

THE FOLLOWING WORK HAS BEEN DONE WITHOUT FIRST OBTAINING A

BUILDING PERMIT:

ENCLOSING THE CARPORT

A STRUCTURE BUILT IN THE REAR YARD

-----

CASE NO: CE03050751 CASE ADDR: 3715 SW 14 ST

OWNER: MANUFACTURERS & TRADERS TRUST CO.

INSPECTOR: KENNETH REARDON

VIOLATIONS: 9-281(b)

THERE IS AN EXCESSIVE GROWTH OF WEEDS AND GRASS IN THE YARD

ALONG WITH TRASH, RUBBISH AND DEBRIS.

9-329(d)

THE BOARD UP CERTIFICATE ISSUED FOR THE PROPERTY HAS NOT BEEN RENEWED NOR HAS THE BUILDING/STRUCTURE BEEN REPAIRED, REHABILITATED, OR SOLD PER THE REQUIREMENTS OF 9-329(d).

FBC 104.1

THE BUILDING HAS BEEN REROOFED WITHOUT FIRST OBTAINING A BUILDING PERMIT.

FBC 104.2.4

THE BATHROOM HAS BEEN REMODELED AND THE WATER HEATER REPLACED WITHOUT FIRST OBTAINING A PLUMBING PERMIT.

CODE ENFORCEMENT BOARD
CITY COMMISSION MEETING ROOM
JUNE 24, 2003
10:00 AM

FBC 3401.6

THE ELECTRICAL METER CAN COVER IS MISSING, LEAVING EXPOSED WIRES. THE EXTERIOR WALL FRAMING IS ROTTED AT THE NORTHEAST CORNER. THERE ARE BROKEN AND MISSING EXTERIOR WALL SHINGLES EXPOSING THE WALL FRAMING TO THE ELEMENTS. THESE BUILDING COMPONENTS ARE NOT BEING MAINTAINED IN A SAFE CONDITION OR IN GOOD WORKING ORDER.

\_\_\_\_\_\_

CASE NO: CE02072217 CASE ADDR: 205 NW 11 AV

OWNER: MASTEN, GREGORY & CYNTHIA

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE INTERIOR AND EXTERIOR OF THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES,

BUT IS NOT LIMITED TO:

A. INSTALLATION OF DOORS

B. INSTALLATION OF REPLACEMENT WINDOWS

CASE NO: CE02111210 CASE ADDR: 725 NW 14 TER

OWNER: TRANSGLOBAL LAND TRUST

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 3401.6

FAILURE TO MAINTAIN THE PROPERTY. WOOD SOFFITS, FASCIA BOARDS, ROOF STRUCTURE, EXTERIOR DOORS AND ELECTRICAL

ELEMENTS REQUIRE REPAIR OR REPLACEMENT.

------

CASE NO: CE03021089 CASE ADDR: 2311 NW 9 PL

OWNER: DAVIES, CAROLYN 1/5 INT

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE INTERIOR OF THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

A. INSTALLATION OF KITCHEN CABINETS

FBC 104.2.4

THERE HAS BEEN MODIFICATIONS TO THE INTERIOR PLUMBING AND DRAIN LINES WITHOUT FIRST OBTAINING THE REQUIRED PERMITS.

FBC 104.2.5

ELECTRICAL RENOVATION, RELOCATION AND NEW INSTALLATION WORK WAS DONE WITHOUT FIRST OBTAINING REQUIRED PERMITS. THIS WORK INCLUDES THE CONNECTIONS TO OUTLETS AND FIXTURES.

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM

JUNE 24, 2003 10:00 AM

\_\_\_\_\_\_

CASE NO: CE03021142
CASE ADDR: 1409 NW 12 ST
OWNER: SANDERS, LAURA
INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT

LIMITED TO:

A. INSTALLATION OF REPLACEMENT WINDOWS AND DOOR.

-----

CASE NO: CE03030326
CASE ADDR: 719 NE 5 TER
OWNER: WATERMAN, EDMUND
INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 3401.6

FAILURE TO MAINTAIN PROPERTY. DETERIORATION OF EXTERIOR WOOD STRUCTURES INCLUDING, BUT NOT LIMITED TO SOFFITS, FASCIA, DOORS, WINDOWS, OVERHANGS AND SIDINGS.

FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

A. INSTALLATION OF EXTERIOR DOORS.

FBC 104.2.5

EXTERIOR WIRING HAS BEEN INSTALLED NOT TO CODE AND REMAINS EXPOSED.

FBC 104.2.11

INSTALLATION OF WALL/WINDOW MOUNTED AIR CONDITIONING UNITS WITHOUT OBTAINING THE PROPER PERMITS.

\_\_\_\_\_\_

CASE NO: CE03031127 CASE ADDR: 1133 NW 2 ST

OWNER: ARREAZA, ALEJANDRO & MEYLIN

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

- A. INSTALLATION OF EXTERIOR DOORS
- B. INTERIOR RENOVATIONS INCLUDING KITCHENS AND BATHS

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM JUNE 24, 2003

10:00 AM

\_\_\_\_\_\_

CASE NO: CE03031694 CASE ADDR: 405 NW 18 AV OWNER: WRIGHT, VANESSA J INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE INTERIOR OF THE BUILDING AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS IN-CLUDES, BUT IS NOT LIMITED TO:

- A. CONVERSION OF LIVING ROOM TO BEDROOM
- B. RELOCATION OF BATHROOM
- C. RELOCATION OF ORIGINAL PARTITION WALLS AND FRAMING

#### FBC 106.1

UNIT OCCUPIED WITHOUT FIRST OBTAINING A CERTIFICATE OF OCCUPANCY FROM THE BUILDING OFFICIAL.

#### 9-281(b)

THE PROPERTY HAS BECOME OVERGROWN AND LITTERED WITH TRASH, RUBBISH AND DEBRIS. THERE ARE ALSO UNLICENSED, INOPERABLE VEHICLES ON THE PROPERTY.

#### FBC 104.2.4

THERE HAVE BEEN MODIFICATIONS TO THE PLUMBING VENTS, FIX-TURES AND DRAIN LINES WITHOUT FIRST OBTAINING THE REQUIRED PERMITS.

#### FBC 104.2.5

ELECTRICAL RENOVATION, RELOCATION AND NEW INSTALLATION WORK WAS DONE WITHOUT FIRST OBTAINING REQUIRED PERMITS. THIS WORK INCLUDES THE CONNECTIONS AND RELOCATIONS OF EXISTING CIRCUITS.

#### FBC 104.2.11

INSTALLATION OF NEW AIR CONDITIONING UNIT WAS INSTALLED WITHOUT FIRST OBTAINING THE REQUIRED PERMITS.

CASE NO: CE03031825 CASE ADDR: 2215 NW 8 ST OWNER: NELSON, THOMAS INSPECTOR: DOUGLAS KURTOCK

#### VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

A. INSTALLATION OF REPLACEMENT WINDOWS.

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM JUNE 24, 2003

10:00 AM

\_\_\_\_\_\_

CASE NO: CE03040437 CASE ADDR: 619 NW 12 AV OWNER: KENNEDY, ARION INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT

LIMITED TO:

A. INSTALLATION OF CARPORT ROOF FRAMING

FBC 3401.6

FAILURE TO MAINTAIN PROPERTY, DETERIORATION OF EXTERIOR WOOD

STRUCTURES INCLUDING SOFFITS, FASCIA AND SIDINGS.

CE03040474 CASE NO:

CASE ADDR: 1131 NW 9 AV
OWNER: PITTMAN, JOYCE 1/2 INT, RHETT, STEPHEN

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND INTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT

LIMITED TO:

A. INSTALLATION OF KITCHEN CABINETS

FBC 104.2.5

THERE HAVE BEEN PHYSICAL ALTERATIONS AND ADDITIONS MADE TO THE EXISTING ELECTRICAL WIRING AND CIRCUITS THROUGHOUT THE INTERIOR OF THE HOUSE WITHOUT OBTAINING THE PROPER PERMITS.

FBC 111.2.1.2.5

ELECTRICAL WORK THAT WAS INSTALLED OR ALTERED IS UNSAFE.

CASE NO: CE03040796 CASE ADDR: 401 NW 13 ST OWNER: CASTANEDA, RAPHAEL INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT

LIMITED TO:

A. INSTALLATION OF FENCE TO EXISTING WALL STRUCTURES.

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM JUNE 24, 2003

10:00 AM

\_\_\_\_\_\_

CASE NO: CE03040968 CASE ADDR: 1617 NW 5 AV

OWNER: THEOPHILE, GERMAINE INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTSINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED

- A. INSTALLATION OF CHAIN-LINK FENCING
- B. ENCLOSURE AND ADDITION TO EXISTING RESIDENCE

CE03041150 CASE NO: CASE ADDR: 900 NW 5 CT

OWNER: TIFT, BOBBIE GAIL LE, WRIGHT, JOHNNIE JR

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 3401.6

FAILURE TO MAINTAIN PROPERTY. DETERIORATION OF EXTERIOR AND INTERIOR STRUCTURES. THE SCOPE OF THIS DETERIORATION INCLUDES, BUT IS NOT LIMITED TO:

- 1. WOOD SOFFITS AND FASCIA
- 2. ROOF SYSTEMS
- 3. STRUCTURAL WINDOW HEADERS
- 4. WINDOW SCREENS
- 5. ELECTRICAL WIRING
- 6. WINDOW SILLS
- 7. ROOF LEAKS
- VERMIN HOLES IN CEILING SPACES 8.
- INTERIOR AIR CONDITIONING UNITS 9.
- 10. CEILING PANELS
- 11. LIGHTING FIXTURES
- 12. CERAMIC TILE SURFACES IN BATHROOMS
- 13. SMOKE DETECTORS
- 14. STUCCO WALL SURFACES
- 15. PLUMBING LEAKS
- 16. STRUCTURAL CRACKS IN MASONRY WALL SECTIONS

#### FBC 104.2.11

THERE HAVE BEEN MODIFICATIONS AND INSTALLATION OF AIR CONDITIONING EQUIPMENT WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

A. INSTALLATION OF WINDOW/WALL MOUNTED AIR CONDITIONING UNITS.

FBC 1016.3.1

EMERGENCY EXIT SIGNS ARE REQUIRED.

### CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM JUNE 24, 2003

10:00 AM

\_\_\_\_\_\_

CASE NO: CE03042097

CASE ADDR: 6363 NW 6 WAY # 155
OWNER: TRICONY CYPRESS ASSOC LTD
INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND INTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

A. DEMOLITION OF INTERIOR OFFICE SPACE CONSISTING OF WALL PARTITIONS, CEILING GRID AND PANELS, FLOORING AND WALL COVERINGS.